Coast Report Ad 2015-09-25: The George: Too Big, Too Risky, Breaks the Rules.

Waterline Resources: "The possibility of an uncontrollable breach of the Gibsons Aquitard" by excavation for the George project "is a MAIN CONCERN".

May 4, 2015 1578-15-001

Town of Gibsons 474 South Fletcher Rd Box 340 Gibsons, BC, VON 1V0 Attention: Andre Boel, Director of Planning

RE: Gibsons Aquifer Review of Geotechnical Investigation Report (Revised) for the Proposed "The George" Mixed Use Development at 377, 385 & 407 Gower Point Road, 397 & 689 Winn Road, and Winn Road Right-of-Way, Gibsons, BC

http://gibsonsalliance.ca/images/gabcdocs/2015-05-04_Waterline_geotech_peer_review_copy_MAIN_CONCENR_UNCONTROLLABLE_BREA CH.pdf

Levelton Engineering: The developer's geotechnical work "does not appear to have considered factors that might result in uncontrolled sinkhole, aquifer depressurization, or ground settlement, any of which could be catastrophic".

07 May 2015

Levelton File # R714-0460-01

Town of Gibsons 474 South Fletcher Road Box 340. Gibsons, BC. VON 1V0

Attention: Mr. Andre Boel, RPP Director of Planning

Project: Geotechnical ReviewHorizon Engineering Inc. Geotechnical Investigation Report - 07

April 2015 Proposed 'The George' Mixed Use Development, Gibsons, BC

http://gibsonsalliance.ca/images/gabcdocs/2015-05-07_Levelton_geotech_peer_review-_Report_copy_COULD_BE_CATSTROPHIC.pdf

Clear Coast Consulting: "Contamination at the Hyak Marine property has not been properly assessed and the proposed George Hotel development presents an unknown, and potentially significant, risk to the environment."

Clear Coast Consulting

May 9, 2014

Mr Avtar Sundher Section Head, Coast Authorizations BC Ministry of Environment Surrey, BC

Re: Improper Contamination Assessment, Hyak Marine property, Gibsons, BC

http://gibsonsalliance.ca/images/gabcdocs/Hyak_Marine_Contamination_-Complaint to BC MoE copy NOT CHARACTERIZED PROPERLY RISK.pdf